



Asbestos Register

Blue Mountains City Council maintains asbestos registers (“registers”) and asbestos management plans (“plans”) relating to each of the buildings owned or occupied by the Council. The registers and plans record information about the existence and location of any known or presumed asbestos containing materials (“ACM”) within those buildings.

The Council’s governing body has adopted the Council’s corporate [asbestos-registers]Asbestos Policy, which is available on our website.

The registers and plans are in two forms. First, the Council maintains a corporate asbestos register and a corporate asbestos management plan. Second, the Council has prepared individual registers and individual plans for each building that contains or may contain ACM. Hardcopies of those individual registers and plans are held in the building concerned.

Whenever work is carried out on a Council building the hardcopy register and the hardcopy plan are each amended by hand, as required. This action ensures that Council employees or contractors who work from time to time within that building have access to accurate information about the ACM that it contains or may contain.

The electronic versions of each of the corporate plans and registers, and of the plans and registers for individual buildings, are periodically updated. However, the key documents are the hardcopy registers and the hardcopy plans for each building which must be inspected before any work is carried out on that building.

NOTES:

- (1) The Council’s electronic registers and plans are valid as dated, and ARE NOT to be relied upon as definitive records and ARE NOT to be used for reference purposes for any construction, demolition, maintenance or any other onsite works. IN ALL CASES, the onsite hardcopy building specific asbestos register and building specific asbestos management plan MUST BE CONSULTED prior to the commencement of physical works on the building concerned. While the electronic versions of the Council’s registers and plans provide guidance concerning the presence or possible presence of ACM it is the onsite hardcopy registers and plans which will remain up to date.
- (2) The Council’s electronic registers and plans relate to Council owned or managed buildings. The electronic registers and plans do not relate to structures (such as picnic shelters, bus shelters and other freestanding structures). Before any work is carried out on such structures the Council’s Hazardous Materials Team (“HMT”) MUST BE CONSULTED. The HMT may be contacted at council@bmcc.nsw.gov.au. The HMT will provide information concerning any ACM that may be present in the structure concerned.

Further information: Further information on safe asbestos management may be obtained by contacting Councils Hazardous Materials Management Team at council@bmcc.nsw.gov.au.



**BLUE MOUNTAINS CITY
COUNCIL**

18/235001

ASBESTOS REGISTER

**WENTWORTH FALLS SCHOOL OF
ARTS AND LIBRARY**

217-219 GREAT WESTERN HIGHWAY

WENTWORTH FALLS



Trim No.	
Rec'd Records	27 NOV 2015 RMCC
REFER	
REMITTANCE	REC No.

Report

ASBESTOS REGISTER

**Blue Mountains City
Council – Stage 3**

**Prepared for:
Blue Mountains City
Council**

**Project No.
28781**

**Date:
25-11-15**

AIRSAFE

93 Beattie Street
Balmain NSW 2041 Australia
T. 02 9555 9034
F. 02 9555 9035
info@airsafe.net.au
www.airsafe.net.au

ABN 85 143 863 496

DISTRIBUTION

Copies	Recipient
2	Daniel Johnston Blue Mountains City Council Strategic Assets Officer Locked Bag 1005 KATOOMBA NSW 2780


© Airsafe OHC Pty Limited [Airsafe]

The information contained in this document is intended for the sole use of the Client identified on the cover sheet for the purpose for which it has been prepared. Airsafe undertakes no duty to or accepts any responsibility for any third party who may rely upon this document.

All rights reserved. No section or element of this document may be removed, reproduced, electronically stored or transmitted in any form without the written permission of Airsafe.

Prepared By:

Reviewed By:



Simon Bice
Consultant

Kieran White
Manager

3.1.34 Asset E00551 – Lomatia Park, Springwood – Shelter Shed/Store93

3.1.35 Asset E00391 – Springwood Cemetery – Shelter, Store and Toilet.....94

3.1.36 Asset D00083 – Springwood Golf Course – Clubhouse95

3.1.37 Asset E00060 – Springwood Golf Course – Machinery and Chemical Storage Shed 101

3.1.38 Asset E00542 – Springwood Council Depot – Carpenters Workshop 103

3.1.39 Asset E00540 – Springwood Council Depot – Garage and Workshop 105

3.1.40 Asset D00144 – Springwood Council Depot – Gardeners Store and Office 106

3.1.41 Asset D00145 – Springwood Council Depot – Garage Office and Amenities 108

3.1.42 Asset E00549 – Springwood Council Depot – Pound Shelter..... 109

3.1.43 Asset D00249 – Springwood Council Depot – Store, Office and Storage Building 110

3.1.44 Asset D00154 – Springwood Council Depot – Trades Foreman Office 115

3.1.45 Springwood Council Depot – Truck Wash..... 116

3.1.46 Asset E00547 – Store 2 – Demountable 117

3.1.47 Asset D00222 – Braemar Gallery, Springwood..... 118

3.1.48 Asset D00258 – Springwood Library 119

3.1.49 Asset NAN113 – Springwood Red Cross Hall..... 122

3.1.50 Asset D00079 – Springwood Tennis Clubhouse 124

3.1.51 Asset D00090 – Sun Valley Pony Clubhouse 127

3.1.52 Asset D00155 – Warrimoo Oval Tennis Clubhouse 130

3.1.53 Asset D00041 – **Wentworth Falls School Of Arts And Library** 132

3.1.54 Asset D00093 – Wentworth Falls Tennis Clubhouse 135

3.1.55 Asset D00146 – Winmalee Tennis Clubhouse – Summerhayes Park 137

3.1.56 Asset E00189 – Woodford Memorial Shelter 139

3.1.57 Asset D0025 – Katoomba Girl Guides Hall 140

3.1.58 Asset D00143– Cottage #1 – Springwood 142

4 RECOMMENDATIONS 145

 4.1 MAINTENANCE 145

 4.2 REMOVAL 148

APPENDIX A – ANALYSIS RESULTS 152

APPENDIX B – PHOTOGRAPHS 170

APPENDIX C – WARNING SIGNS AND LABELS 262

Location	Asbestos	
	Bonded	Friable
Asset NAN113 – Springwood Red Cross Hall	×	×
Asset D00079 – Springwood Tennis Clubhouse	✓	×
Asset D00090 – Sun Valley Pony Clubhouse	×	×
Asset D00155 – Warrimoo Oval Tennis Clubhouse	×	×
Asset D00041 – Wentworth Falls School Of Arts And Library	✓	×
Asset D00093 – Wentworth Falls Tennis Clubhouse	×	×
Asset D00146 – Winmalee Tennis Clubhouse – Summerhayes Park	×	×
Asset E00189 – Woodford Memorial Shelter	✓	×
Asset D0025 – Katoomba Girl Guides Hall	×	×
Asset – Cottage #1 – Springwood	✓	×

Airsafe recommends that for items identified in the asbestos register requiring action refer to Section 4.

Any areas, which include asbestos containing materials, should be signposted with warning signs to ensure that the asbestos is not unknowingly disturbed without the correct precautions being taken.

The asbestos register, including any risk assessments, should be reviewed every 12 months or earlier.

Asset	Inaccessible Area
Asset D00041 – Wentworth Falls School Of Arts And Library	3302 Sub-floor
	3303 Electrical Control Room
	3304 Library – ceiling space
	3305 Theatre – ceiling space
Asset E00189 – Woodford Memorial Shelter	Ceiling space
Asset D00143– Cottage #1 – Springwood	Sub-floor (limited access)

Care should be taken if future refurbishment, demolition or maintenance works need to access these areas.

1.6 LIMITATIONS

This report has been prepared to meet the requirements outlined in the scope of work. It does not include evaluation of any other issues. Airsafe performed the services in a professional manner, in accordance with relevant guidelines and standards, and generally accepted industry practices. Airsafe does not make any other warranty, expressed or implied, as to the professional advice contained in this report.

The survey was based on a visual inspection of the specified areas. It should be noted that this assessment is reflective of the current site conditions and cannot be regarded as absolute without extensive invasion of structures. Only materials that were physically accessible at the time of inspection were sampled. Consequently, without substantial demolition of the building, it is not possible to guarantee that every ACM has been located. Care should be taken during the course of normal site works, refurbishment or demolition works when entering any previously inaccessible areas. If suspect materials are encountered, works should cease in the area until samples have been collected and analysed by competent personnel.

The presence of any residual asbestos materials from prior removal works cannot always be ascertained without extensive intrusive investigation which has not been undertaken as part of this survey.

As the buildings were in use at the time of inspection, only non-destructive sampling techniques were used. The survey is not intended for use or referral for the purpose of demolition, refurbishment, renovations or structural alterations. In the event of future demolition, refurbishment, renovation or structural alterations further investigation, which may entail destructive testing, shall be required.

It should be noted that the sampling program was limited to the collection of representative samples of suspect materials for analysis. Other materials of similar appearance are assumed to have a similar content.

The control measures required for identified and presumed ACM should be determined from the risk assessment and should follow the following principles:

- Control Measure 1 -** If the ACM are friable and not in a stable condition, and there is a risk to health from exposure, they should be removed by an asbestos removalist as soon as practicable.
- Control Measure 2 -** If the ACM are friable but are in a stable condition and are accessible, serious consideration should be given to their removal. If the removal is not immediately practicable, short-term control measures, such as sealing and enclosure, may be able to be used until removal is possible.
- Control Measure 3 -** If the ACM are not friable and are in a good, stable condition, minimising disturbance and encapsulation may be appropriate controls.
- Control Measure 4 -** Any remaining ACM should be clearly labeled, where possible, and regularly inspected to ensure they are not deteriorating or otherwise contributing to an unacceptable health risk.

These control measures reflect the following hierarchy of controls:

- 1 - Elimination/removal (most preferred);
- 2 - Isolation/enclosure/sealing;
- 3 - Engineering controls;
- 4 - Safe Work Practices (administrative controls); and
- 5 - Personal Protective Equipment (PPE) (least preferred).

ACM need to be removed before demolition, partial demolition, renovation or refurbishment if they are likely to be disturbed by those works in accordance with the Code of Practice: How to Safely Remove Asbestos [Safe Work Australia, 2011].

3.1.53 Asset D00041 – Wentworth Falls School Of Arts And Library

Address: 217-219 Great Western Highway, Wentworth Falls

Inspection Date: 23/10/15

Inspected By: Simon Bice

Location	Material	Sample ID	Sample Status	Photo No.	Asbestos Classification	Condition	Accessibility	Re-inspect	Current Label	Control Measure	Record of Works Undertaken
Asset D00041 – Wentworth Falls School Of Arts And Library											
External											
Window Frames throughout – mastic 2247	Mastic	28781-53-1	Negative	-	-	-	-	-	-	-	-
Theatre – Entrance – awning lining 2248	Fibreboard	28781-53-2	Negative	-	-	-	-	-	-	-	-
Theater – Entrance – Flashing linings –eastern/western perimeters 2249	Fibreboard	28781-53-3	Negative	-	-	-	-	-	-	-	-
Theater – Entrance – Roof area – flashing 2250	Fibreboard	Similar to 28781-53-3	Assumed Negative	-	-	-	-	-	-	-	-

Location	Material	Sample ID	Sample Status	Photo No.	Asbestos Classification	Condition	Accessibility	Re-inspect	Current Label	Control Measure	Record of Works Undertaken
Theatre – northern perimeter windows – infill panels below 2251	Fibreboard	28781-53-4	Negative	-	-	-	-	-	-	-	-
Internal											
Library – ceiling lining 2252	Plaster	-	-	-	-	-	-	-	-	-	-
Theatre – Entrance Area – western area – linoleum 2253	Linoleum	Not suspect	-	-	-	-	-	-	-	-	-
Theatre – entrance to storeroom adjacent entrance area – fire door 2254	Fire door core	Fire Control Doors – tag on hinge indicates installation in 1999	Assumed Negative	-	-	-	-	-	-	-	-
Theatres – Seating Area – ceiling lining 314	-	No access due to height restrictions	Confirm status once access available	-	-	-	-	-	-	-	-
Theatre – Stage Area – fascia/gable lining 2255	Fibreboard	28781-53-5	Negative	-	-	-	-	-	-	-	-
Theatre – Stage Area – northern and southern perimeters – western internal wall cladding 2256	Fibreboard	28781-53-6	Negative	-	-	-	-	-	-	-	-

Location	Material	Sample ID	Sample Status	Photo No.	Asbestos Classification	Condition	Accessibility	Re-inspect	Current Label	Control Measure	Record of Works Undertaken
Theatre – Stage Area – northern and southern perimeters – western upper internal wall cladding 313	Fibrous cement sheeting	28781-53-7	Positive	170	Bonded	Stable	Low	November 2020	Not labeled	4	
Theatre – Stage Area – Lower Level – Chang rooms – toilet – internal wall cladding 2257	Fibreboard	28781-53-8	Negative	-	-	-	-	-	-	-	-
Theatre – Stage Area – Lower Level – Chang rooms – toilet – external wall cladding 2258	Fibreboard	Similar to 28781-53-8	Assumed Negative	-	-	-	-	-	-	-	-
Hall Area – ceiling linings throughout 2259	Plaster	-	-	-	-	-	-	-	-	-	-
Hall Area – eastern entrance doorway to main central hall – ceiling lining 2260	Fibreboard	Similar to 28781-53-9	Assumed Negative	-	-	-	-	-	-	-	-
Hall Area – eastern entrance doorway to main central hall – external wall cladding 2261	Fibreboard	28781-53-9	Negative	-	-	-	-	-	-	-	-
Hall Area – eastern entrance doorway to main central hall – internal wall cladding 2262	Fibreboard	Similar to 28781-53-9	Assumed Negative	-	-	-	-	-	-	-	-

APPENDIX A – ANALYSIS RESULTS

TEST REPORT

November 25, 2015

Blue Mountains City Council
Locked Bag 1005
KATOOMBA NSW 2780Your Reference: Blue Mountains City Council – Stage 3
Job Number: 28781**Attention:** Daniel Johnston

Dear Daniel,

In accordance with your instructions, Airsafe tested samples from the above site for asbestos content.

The following samples were processed on the dates indicated.

Samples:	Sample's
Date of Sampling:	07/10/15-11/11/15
Date of Analysis:	08/10/15-12/11/15
Date of Preliminary Report Sent:	Not Issued

The results and associated quality control are contained in the following pages of this report.

Should you have any queries regarding this report please contact the undersigned.

Yours faithfully
AIRSAFE OHC PTY LIMITEDKieran White
Manager

PROJECT: Blue Mountains City Council – Stage 3

JOB NO: 28781

28781-50-5	Springwood Tennis Clubhouse – Internal – Male Toilets – ceiling lining	9x8x1mm fibreboard fragment	Chrysotile asbestos detected Organic fibres detected
28781-50-6	Springwood Tennis Clubhouse – Internal – Male Toilets – Entrance Room – ceiling lining	5x4x1mm fibreboard fragment	Chrysotile asbestos detected Organic fibres detected
28781-51-1	Sun Valley Pony Clubhouse – External – awning lining	25x11x4mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-51-2	Sun Valley Pony Clubhouse – Internal – Main Room – ceiling lining	13x5x2mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-52-1	Warrimoo Oval Tennis Clubhouse – External – eave linings	8x4x1mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-52-2	Warrimoo Oval Tennis Clubhouse – External – gable ends	16x5x2mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-52-3	Warrimoo Oval Tennis Clubhouse – External – awning lining	6x4x2mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-52-4	Warrimoo Oval Tennis Clubhouse – Internal – ceiling lining	6x4x1mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-52-5	Warrimoo Oval Tennis Clubhouse – Internal – external wall cladding of disabled toilet	8x5x2mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-53-1	Wentworth Falls School Of Arts And Library – External – Window Frames – mastic	6x4x2mm window putty fragment	No asbestos detected
28781-53-2	Wentworth Falls School Of Arts And Library – External – Theatre – Entrance – awning lining	15x8x2mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-53-3	Wentworth Falls School Of Arts And Library – External – Theater – Entrance – eastern perimeter - flashing	33x14x3mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-53-4	Wentworth Falls School Of Arts And Library – External – Theatre – northern perimeter windows – infill panels below	13x4x1mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-53-5	Wentworth Falls School Of Arts And Library – Internal – Theatre – Stage Area – fascia/gable lining	8x6x1mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-53-6	Wentworth Falls School Of Arts And Library – Internal – Theatre – Stage Area – northern perimeters – western internal wall cladding	23x9x2mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-53-7	Wentworth Falls School Of Arts And Library – Internal – Theatre – Stage Area – northern perimeters – upper western internal wall cladding	4x3x2mm fibrous cement sheet fragment	Chrysotile asbestos detected
28781-53-8	Wentworth Falls School Of Arts And Library – Internal – Theatre – Stage Area – Lower Level – Change rooms – toilet – internal wall cladding	13x9x2mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-53-9	Wentworth Falls School Of Arts And Library – Internal – Hall Area – eastern entrance doorway to main central hall – external wall cladding	9x6x1mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-54-1	Wentworth Falls Tennis Clubhouse – External – eave linings	5x5x1mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-54-2	Wentworth Falls Tennis Clubhouse – External – Patio – awning lining	6x5x2mm fibreboard fragment	No asbestos detected Organic fibres detected
28781-53-3	Wentworth Falls Tennis Clubhouse – Internal – Main Room – upper western wall (above kitchen)	8x6x1mm fibreboard fragment	No asbestos detected Organic fibres detected





Photo 170: Asset D00041 – Wentworth Falls School Of Arts And Library – Theatre – Stage – northern and southern perimeters – asbestos cement sheet western upper internal wall cladding.

APPENDIX C – WARNING SIGNS AND LABELS

