

Asbestos Register

Blue Mountains City Council maintains asbestos registers (“registers”) and asbestos management plans (“plans”) relating to each of the buildings owned or occupied by the Council. The registers and plans record information about the existence and location of any known or presumed asbestos containing materials (“ACM”) within those buildings.

The Council’s governing body has adopted the Council’s corporate [asbestos-registers] Asbestos Policy, which is available on our website.

The registers and plans are in two forms. First, the Council maintains a corporate asbestos register and a corporate asbestos management plan. Second, the Council has prepared individual registers and individual plans for each building that contains or may contain ACM. Hardcopies of those individual registers and plans are held in the building concerned.

Whenever work is carried out on a Council building the hardcopy register and the hardcopy plan are each amended by hand, as required. This action ensures that Council employees or contractors who work from time to time within that building have access to accurate information about the ACM that it contains or may contain.

The electronic versions of each of the corporate plans and registers, and of the plans and registers for individual buildings, are periodically updated. However, the key documents are the hardcopy registers and the hardcopy plans for each building which must be inspected before any work is carried out on that building.

NOTES:

- (1) The Council’s electronic registers and plans are valid as dated, and ARE NOT to be relied upon as definitive records and ARE NOT to be used for reference purposes for any construction, demolition, maintenance or any other onsite works. IN ALL CASES, the onsite hardcopy building specific asbestos register and building specific asbestos management plan MUST BE CONSULTED prior to the commencement of physical works on the building concerned. While the electronic versions of the Council’s registers and plans provide guidance concerning the presence or possible presence of ACM it is the onsite hardcopy registers and plans which will remain up to date.
- (2) The Council’s electronic registers and plans relate to Council owned or managed buildings. The electronic registers and plans do not relate to structures (such as picnic shelters, bus shelters and other freestanding structures). Before any work is carried out on such structures the Council’s Hazardous Materials Team (“HMT”) MUST BE CONSULTED. The HMT may be contacted at council@bmcc.nsw.gov.au. The HMT will provide information concerning any ACM that may be present in the structure concerned.

Further information: Further information on safe asbestos management may be obtained by contacting Councils Hazardous Materials Team at council@bmcc.nsw.gov.au.



Lomatia Park - Amenities Block

Asbestos/Lead Register & Management Plan

Asbestos Register/Lead and Management Plan

Policy Ref. No:	25132	Staff Consultative Committee Endorsement Date:	N/A
HPE Record No:	18/17876	Meeting Date:	N/A
Distribution:	Insite Delivery/Online	Endorsement Date:	ELT Meeting Date
Status:	Approved		
Scope:	Tenants, Facility Users, Community	Governing Policy:	Asbestos Policy
Lifespan:	5 years or following legislative change	Responsible Directorate/Group:	Economy Place & Infrastructure/Property and Commercial Services
Next review:	5 years from adoption	Contact Position:	Program Leader Hazardous Materials Team

DOCUMENT CONTROL

DOCUMENT NO.	DATA ENTRY		APPROVED & AUTHORISED	
	DATE	PERSONNEL	DATE	PERSONNEL
Lomatia Park34468011 12022HMMR	01/11/2022	Luke Trevena	20/12/2022	Jason Adams

PREVIOUS DOCUMENTATION

REPORT#	COMPANY	DATE
18/17876	EnviroScience	08/12/2017

This document was prepared in accordance with Blue Mountains City Council Quality Policy and System, which is based on Australian Standard / NZS ISO 9001. It is issued subject to review and authorisation by approved signatories. It has been prepared for the particular requirements of Blue Mountains City Council based on a specific brief. It is not intended for and should not be relied upon by a third party, and should not be redistributed without written consent from YOUR COMPANY NAME. The information contained within this document should not be reproduced, presented or reviewed except in full. Prior to passing on to a third party, Blue Mountains City Council is to fully inform the third party of the specific brief and limitations associated with the commission.

Contents

1. Executive Summary.....	6
2. Introduction.....	7
I. Building Information.....	7
II. Scope of Works.....	7
III. Risk Category.....	8
3. How to use this report.....	9
4. Sampling Methodology.....	9
Asbestos Containing Materials.....	9
Lead Containing Paint.....	9
Lead Containing Dust.....	10
5. Asbestos/Lead Materials Register.....	11
6. Risk Matrix.....	16
IV. Recommendation Action Codes.....	16
V. Specific Criteria.....	17
Lead Containing Paint.....	17
Lead Dust.....	17
VI. Risk Assessment.....	17
VII. Materials Assessment.....	19
Product Type.....	19
Extent of Damage.....	19
Surface Type.....	19
VIII. Likelihood of Disturbance.....	20
Occupant Activity.....	20
Likelihood of Disturbance.....	20
Human Exposure Potential.....	21
Appendix A (Photographs).....	22
Appendix B (Site Plan - Map).....	25
Appendix C (Analysis Report).....	26
Inaccessible Areas.....	36

Standard access limitation to survey type (non-destructive).....	37
7. Responsibilities.....	38
IX. Controller of Premises	38
X. Special Responsibilities - Asbestos	38
XI. Employers.....	39
XII. Employees & Contractors	40
XIII. Asbestos Consultant	40
XIV. Asbestos Removalists.....	41
XV. Lead Containing Paint	41
8. Awareness & Training	42
9. Signage	42
10. Review	44
11. Emergency Procedures	44
12. Legislation, Codes & Standards	46
XVI. Legislation.....	46
XVII. Code of Practice.....	46
XVIII. Standards	46
13. Terms & Definitions	47

1. Executive Summary

Blue Mountains City Council conducted Hazardous Materials Management Register for the workplace located at 32-34 Bland Road Springwood NSW 2777.

The inspection was conducted on 01/11/2022, and the following items were identified:

ASBESTOS

Location	Material Description	Risk Rating
External / GF / Exterior / West / Eaves, Perimeter of electrical room	Fibre Cement Sheet	Very Low
External / GF / Exterior / Eaves, Perimeter of main amenities	Fibre Cement Sheet	Very Low
Internal / GF / Central (north) storeroom (Cricket storeroom) / Ceiling	Fibre Cement Sheet	Very Low
Internal / GF / Central (south) storeroom (Dog club) / Ceiling	Fibre Cement Sheet	Very Low
Internal / GF / Electrical board room (western side) / Ceiling	Fibre Cement Sheet	Very Low
Internal / GF / Men's toilet / Ceiling	Fibre Cement Sheet	Very Low
Internal / GF / North west corner storeroom/toilet / Ceiling	Fibre Cement Sheet	Very Low
Internal / GF / South West Room (kitchen) / Ceiling	Fibre Cement Sheet	Very Low
Internal / GF / Storeroom adjacent dog club (south) / Ceiling	Fibre Cement Sheet	Very Low
Internal / GF / Women's toilet / Ceiling	Fibre Cement Sheet	Very Low

LEAD PAINT

Location	Material Description	Risk Rating
External / GF / Exterior / External / External cream paint system	Cream - Topcoat	Very Low
External / GF / Exterior / External / External green paint system	Green - Topcoat	Very Low

2. Introduction

I. Building Information

ASSET #	34468
WORKPLACE NAME	Amenities Block
WORKPLACE ADDRESS	32-34 Bland Road Springwood NSW 2777
WORKPLACE DESCRIPTION	Amenities Block
APPROXIMATE AGE	1960

II. Scope of Works

REPORT TYPE	Hazardous Materials Management Register
THE CLIENT	Blue Mountains City Council
AREA COVERED BY THE SCOPE	Amenities Block
LEAD SURVEYOR	Luke Trevena
ASSISTANT SURVERYOR	-
INSPECTION DATE	01/11/2022

This Asbestos/Lead Management Plan has been developed by [Blue Mountains City Council](#) and in full accordance with NSW Work Health & Safety Regulation 2017

III. Risk Category

The asbestos/lead materials identified in this report have been assessed, given a Risk Category as outlined below and must be managed in full accordance with the Asbestos Management Plan.

Risk Category	Control Descriptor
A1	Restrict Access & Remove
	<ul style="list-style-type: none"> • Friable or poorly bonded to substrate, located in accessible areas. • Severely water damaged or unstable • Further damage or deterioration likely • Asbestos debris and stored asbestos in reasonably accessible areas
A2	Enclose, Encapsulate or Seal by Licensed Contractor - Re-Inspect Periodically
	<ul style="list-style-type: none"> • Damaged material in reasonably accessible areas • Friable or poorly bonded to substrate, with bonding achievable. • Possibility of disturbance through contact • Possibility of deterioration through weathering
A3	Remove During Refurbishment or Maintenance. Enclose, Encapsulate or Seal by General Maintenance Contractors, Re-Inspect Periodically
	<ul style="list-style-type: none"> • Asbestos debris or stored material in rarely accessed areas • Further disturbance or damage unlikely, other than during maintenance or service • Asbestos friction materials, gaskets and brake linings
A4	No remedial Action Re-Inspect Periodically
	<ul style="list-style-type: none"> • Firmly bonded to substrate and readily visible for inspection • Inaccessible and fully contained • Stable and damage unlikely
A5	No Action Required - No ACM Identified

Should ACM be disturbed, the area must be isolated and an assessment by council's Competent Person or an independent assessment by an Occupational Hygienist or Licensed Asbestos Assessor must be undertaken and may coupled with airborne asbestos air monitoring.

It is expressly prohibited for any person other than a duly authorised Council Employee or engaged contractor to remove, handle, treat, dispose of or disturb ACM on a council owned asset. Should maintenance works be required on ACM or disturbed ACM is identified, then council must be advised immediately on **4780 5000**

3. How to use this report

This report is an **Asbestos/Lead Materials Register (ALMR) and Asbestos/Lead Management Plan (ALMP)** for the location specified at Section 2 of this report. It covers the management of Asbestos Containing Materials (ACM), Lead Containing Paint (LCP) and Lead Containing Paint (LCP) which has been identified via an inspection process undertaken by the company detailed in Section 2 and this AMP must be read in conjunction with the above-mentioned ALMR.

The purpose of this ALMP is to ensure full compliance with the legislative and regulatory requirements intrinsic to Asbestos and Lead Management in NSW, including compliance with NSW Code of Practice How to manage and control asbestos in the workplace.

The person with management or control of the workplace must ensure this ALMR and ALMP is kept at the workplace and be readily accessible.

It is a requirement that any activity at this location involving the removal or encapsulation of any material listed in the Asbestos Register is recorded and signed off (Refer to Document Control on Page 2).

All Asbestos and Lead Related works must be consulted with Council prior to any works being undertaken in order to ensure that the works are completed to a satisfactory standard in accordance with relevant codes, standards and guidelines.

To fulfil WHS obligations and to aid in the identification and management of lead paint and lead containing dust, Blue Mountains City Council has included lead paint/dust in the register.

Any queries regarding the interpretation and/or implementation of this Management Plan should be directed to Council **4780 5000**

4. Sampling Methodology

Asbestos Containing Materials

Suspected ACM were sampled by surveyor in accordance with AS4964:2004 *Method for the qualitative identification of asbestos in bulk samples* Where collected, representative samples were placed into clip-lock plastic bags and analysed by an external NATA-accredited laboratory for the presence of asbestos by polarised light microscopy and dispersion staining techniques.

Lead Containing Paint

Suspected LCP were sampled by surveyor in accordance with AS/NZS 4361.2:2017 *Guide to hazardous paint management, Part 2: Lead paint in residential, public and commercial buildings*. Where collected, representative samples of paint were placed in a clip-lock plastic bags and then analysed internally, by NATA-accredited laboratory for determination of lead concentration.

Lead Containing Dust

Where general settled dust suspected of containing lead were identified, samples were collected by surveyor in accordance with AS/NZS4361.2:2017. An area of 100 cm² (10 x 10 cm²) or 900cm² (30 x 30 cm²) was marked out using a disposable template. A "Ghost Wipe" was then used to collect the sample. The wipe was placed flat onto the surface in one corner of the area to be sampled and rubbed across the entire area in an 'S' pattern. The wipe was re-folded so that the collected dust was on the inside and again rubbed across the area at 90° to the first 'S'. The wipe was again folded with the dust inside and placed in a clip-lock plastic bag.

Where bulk accumulated dusts suspected of containing lead were identified, samples were collected by surveyor using a metal spatula by scraping approximately 5 g of dust into a clip-lock plastic bag.

All samples were allocated a unique sample identification number and the location noted.

Collected samples were then analysed by an external NATA-accredited laboratory for determination of lead concentration by atomic absorption spectroscopy techniques.

5. Asbestos/Lead Materials Register

EXTERNAL - GF - EXTERIOR

Photo #	REF #	HAZARD	RESULT	SPECIFIC LOCATION	MATERIAL	QUANTITIY	FRIABILITY	OVERALL RISK	ACTION CODE	TIMEFRAME	COMMENTS
1	Previously sampled, same as B17399S01	Asbestos	Chrysotile & Amosite Asbestos detected	Eaves, Perimeter of electrical room	Fibre Cement Sheet	5 m ²	Non-Friable	Very Low	A4	5 Yearly Reinspection	-
2	Previously sampled B17399S01	Asbestos	Chrysotile & Amosite Asbestos detected	Eaves, Perimeter of main amenities	Fibre Cement Sheet	25 m ²	Non-Friable	Very Low	A3	As soon as reasonably practicable	Eave damaged
3	Previously sampled 17399-S05	Lead	Lead Detected (1.0%w/w)	External cream paint system	Cream - Topcoat	30 m ²	Not Applicable	Very Low	A4	5 Yearly Reinspection	-
4	437871-LP01	Lead	Lead detected (1.6%w/w)	External green paint system	Green - Topcoat	40 m ²	Not Applicable	Very Low	A4	5 Yearly Reinspection	-

INTERNAL - GF - CENTRAL (NORTH) STOREROOM (CRICKET STOREROOM)

Photo #	REF #	HAZARD	RESULT	SPECIFIC LOCATION	MATERIAL	QUANTITIY	FRIABILITY	OVERALL RISK	ACTION CODE	TIMEFRAME	COMMENTS
5	Previously sampled, similar to B17399S02	Asbestos	Chrysotile & Amosite Asbestos detected	Ceiling	Fibre Cement Sheet	40 m ²	Non-Friable	Very Low	A4	5 Yearly Reinspection	-

INTERNAL - GF - CENTRAL (SOUTH) STOREROOM (DOG CLUB)

Photo #	REF #	HAZARD	RESULT	SPECIFIC LOCATION	MATERIAL	QUANTITIY	FRIABILITY	OVERALL RISK	ACTION CODE	TIMEFRAME	COMMENTS
6	Previously sampled, similar to B17399S02	Asbestos	Chrysotile & Amosite Asbestos detected	Ceiling	Fibre Cement Sheet	40 m ²	Not Applicable	Very Low	A4	5 Yearly Reinspection	-

INTERNAL - GF - ELECTRICAL BOARD ROOM (WESTERN SIDE)

Photo #	REF #	HAZARD	RESULT	SPECIFIC LOCATION	MATERIAL	QUANTITIY	FRIABILITY	OVERALL RISK	ACTION CODE	TIMEFRAME	COMMENTS
7	Previously sampled, similar to B17399S02	Asbestos	Chrysotile & Amosite Asbestos detected	Ceiling	Fibre Cement Sheet	6 m ²	Non-Friable	Very Low	A4	5 Yearly Reinspection	-
8	Visually identified	Asbestos	No Asbestos	Wall	Electrical backing board	1 Unit	Not Applicable	-	A5	-	Modern electrical backing board

Photo #	REF #	HAZARD	RESULT	SPECIFIC LOCATION	MATERIAL	QUANTITIY	FRIABILITY	OVERALL RISK	ACTION CODE	TIMEFRAME	COMMENTS
			Detected								

INTERNAL - GF - INTERIOR

Photo #	REF #	HAZARD	RESULT	SPECIFIC LOCATION	MATERIAL	QUANTITIY	FRIABILITY	OVERALL RISK	ACTION CODE	TIMEFRAME	COMMENTS
-	Previously sampled, B17399-S06	Lead	Lead Not Detected (<0.05%w/w)	Internal cream paint system throughout	Cream - Topcoat	25 m ²	Not Applicable	-	A5	-	-

INTERNAL - GF - MEN'S TOILET

Photo #	REF #	HAZARD	RESULT	SPECIFIC LOCATION	MATERIAL	QUANTITIY	FRIABILITY	OVERALL RISK	ACTION CODE	TIMEFRAME	COMMENTS
9	Previously sampled, similar to B17399S02	Asbestos	Chrysotile & Amosite Asbestos detected	Ceiling	Fibre Cement Sheet	10 m ²	Non-Friable	Very Low	A4	5 Yearly Reinspection	-
10	Previously sampled B17399S04	Asbestos	No Asbestos Detected	Men's toilet cistern	Moulded Fibre Cement	1 Unit	Not Applicable	-	A5	-	-
-	Previously sampled	Asbestos	No Asbestos	Mens urinal cistern	Moulded Fibre Cement	1 Unit	Not Applicable	-	A5	-	-

Photo #	REF #	HAZARD	RESULT	SPECIFIC LOCATION	MATERIAL	QUANTITIY	FRIABILITY	OVERALL RISK	ACTION CODE	TIMEFRAME	COMMENTS
	B17399S03		Detected								

INTERNAL - GF - NORTH WEST CORNER STOREROOM/TOILET

Photo #	REF #	HAZARD	RESULT	SPECIFIC LOCATION	MATERIAL	QUANTITIY	FRIABILITY	OVERALL RISK	ACTION CODE	TIMEFRAME	COMMENTS
11	Previously sampled, similar to B17399S02	Asbestos	Chrysotile & Amosite Asbestos detected	Ceiling	Fibre Cement Sheet	10 m ²	Non-Friable	Very Low	A4	5 Yearly Reinspection	-

INTERNAL - GF - SOUTH WEST ROOM (KITCHEN)

Photo #	REF #	HAZARD	RESULT	SPECIFIC LOCATION	MATERIAL	QUANTITIY	FRIABILITY	OVERALL RISK	ACTION CODE	TIMEFRAME	COMMENTS
12	Previously sampled B17399S02	Asbestos	Chrysotile & Amosite Asbestos Detected	Ceiling	Fibre Cement Sheet	8 m ²	Non-Friable	Very Low	A4	5 Yearly Reinspection	-

INTERNAL - GF - STOREROOM ADJACENT DOG CLUB (SOUTH)

Photo #	REF #	HAZARD	RESULT	SPECIFIC LOCATION	MATERIAL	QUANTITIY	FRIABILITY	OVERALL RISK	ACTION CODE	TIMEFRAME	COMMENTS
-	Previously sampled, similar to B17399S02	Asbestos	Chrysotile & Amosite Asbestos detected	Ceiling	Fibre Cement Sheet	10 m ²	Non-Friable	Very Low	A4	5 Yearly Reinspection	-

INTERNAL - GF - WOMEN'S TOILET

Photo #	REF #	HAZARD	RESULT	SPECIFIC LOCATION	MATERIAL	QUANTITIY	FRIABILITY	OVERALL RISK	ACTION CODE	TIMEFRAME	COMMENTS
13	Previously sampled, similar to B17399S02	Asbestos	Chrysotile & Amosite Asbestos detected	Ceiling	Fibre Cement Sheet	10 m ²	Non-Friable	Very Low	A4	5 Yearly Reinspection	-
14	Previously sampled B17399-S7	Asbestos	No Asbestos Detected	Women's toilet cistern	Moulded Fibre Cement	3 Units	Not Applicable	-	A5	-	-

6. Risk Matrix

IV. Recommendation Action Codes

Following the risk assessment of building materials for asbestos containing material an action score is assigned for recommended best practice to control the risk presented by the material. The action score will be assigned according to the surveyor's assessment of the situation at the time of the survey.

The Overall Risk Assessment Score is a quantitative assessment determined by the sum of the scores based on the material assessment and the likelihood of exposure; i.e. Risk Score = Material Score + Location Score (out of as possible 18).

Overall Risk Assessment Score	Risk Category	Control Descriptor
14-18	A1	Restrict Access & Remove
		<ul style="list-style-type: none"> Friable or poorly bonded to substrate, located in accessible areas. Severely water damaged or unstable Further damage or deterioration likely Asbestos debris and stored asbestos in reasonably accessible areas
9-13	A2	Enclose, Encapsulate or Seal by Licensed Contractor - Re-Inspect Periodically
		<ul style="list-style-type: none"> Damaged material in reasonably accessible areas Friable or poorly bonded to substrate, with bonding achievable. Possibility of disturbance through contact Possibility of deterioration through weathering
5-8	A3	Remove During Refurbishment or Maintenance. Enclose, Encapsulate or Seal by General Maintenance Contractors, Re-Inspect Periodically
		<ul style="list-style-type: none"> Asbestos debris or stored material in rarely accessed areas Further disturbance or damage unlikely, other than during maintenance or service Asbestos friction materials, gaskets and brake linings
0-4	A4	No remedial Action Re-Inspect Periodically
		<ul style="list-style-type: none"> Firmly bonded to substrate and readily visible for inspection Inaccessible and fully contained Stable and damage unlikely
	A5	No Action Required - No Asbestos/Lead Identified

Table 1 – Risk Scores and action codes

The following hierarchy of controls should be consulted when implementing control measures to eliminate the risks arising from hazardous materials.

- Elimination/removal;
- Isolation/enclosure/sealing;
- Engineering Controls;
- Safe Work Practices (administrative controls); and
- Personal Protective Equipment.

A combination of these controls may be required in order to manage hazardous materials.

In consideration of the Hierarchy of Controls, preferential consideration must be given to removing hazardous materials during renovation, refurbishment and maintenance activities etc. where removal is practicable.

Areas of a workplace that contain ACM including plant, equipment and components should be signposted with appropriate warning signs to ensure that hazardous materials are not unknowingly disturbed without the correct precautions being implemented.

Signage should be placed at all entrances to the work areas where ACM is present and must conform to Australian Standard 1319-1994 *Safety Signs for the Occupational Environment*. The number of labels and the location of signage are to be determined by a competent person and may take into consideration the usage of areas and public access.

V. Specific Criteria

Lead Containing Paint

AS/NZS4361.2:2017 defines lead content in excess of 0.1 percent by weight of the dry film determined by laboratory testing to be LCP. Results were expressed in percent weight per weight (%w/w).

Lead Dust

Lead swab samples were taken in accordance with Section 5.6: Clearance testing and Appendix C: Standard Practice for Determining of Lead in Surface Dust of AS/NZS4361.2-2017 Guide to lead paint management Residential and commercial buildings. This guidance document stipulates the following lead dust loadings for clearance purposes:

- 1mg/m² for interior floors
- 5mg/m² for interior window sills, and
- 8mg/m² for exterior surfaces

Should the area be due for demolition, other avenues of control and remediation can be considered as part of an overall demolition occupational health and safety management plan to reduce the risk to workers without having to achieve the clearance levels above.

VI. Risk Assessment

The risk assessment is explained, in table 1. The semi-quantitative risk assessment borrows elements from the materials risk assessment documented in HSG264: Asbestos: The survey guide – HSE and the priority risk assessment documented in HSG 227: A comprehensive guide to Managing Asbestos in premises – HSE, providing an element of quantification to the qualitative nature of site risk assessment.

Some of the elements of these well-documented risk assessments have been omitted. Most notably the asbestos type from the materials risk assessment, as all types of asbestos are listed by the International Agency for Research on Cancer (IARC) as Type 1 Carcinogens. In addition note the emittance of the maintenance activity from HSG 277. The reason being that human risk factors associated with maintenance activities are often difficult to assess in-situ and require detailed input from the Person in Control of a Business of Undertaking (PCBU).

The risk assessment then takes into account all other Hazardous materials and utilizes the similar algorithms to create a risk assessment for those materials.

An explanation of the material assessment and likelihood of exposure scores can be found in the further below.

VII. Materials Assessment

Product Type

EXAMPLES OF MATERIALS – ASBESTOS	EXAMPLES OF MATERIALS – LEAD	SCORE
Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc)	Lead paint, Lead Compounds/Alloys/Products	1
Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt	Lead paint flakes	2
Thermal insulation (eg pipe and boiler lagging), sprayed asbestos, loose asbestos, asbestos mattresses and packing	Lead dust	3

Table 2 - Product Type (or debris)

Extent of Damage

EXAMPLES OF MATERIALS - ASBESTOS	EXAMPLES OF MATERIALS – LEAD	SCORE
Good condition: no visible damage	Good condition: no visible damage	0
Low damage: a few scratches or surface marks; broken edges on boards, tiles etc	Peeling paint, Large paint flakes	1
Medium damage: significant breakage of materials or several small areas where material has been damaged revealing loose asbestos fibres	Large amounts of fine flaking paint and debris	2
High damage or delamination of materials, sprays and thermal insulation. Visible asbestos debris.	Visible debris, Lead dust	3

Table 3 - Extent of the Damage or Deterioration

Surface Type

EXAMPLES OF MATERIALS - ASBESTOS	EXAMPLES OF MATERIALS – LEAD	SCORE
Composite materials containing asbestos: reinforced plastics, resins, vinyl tiles	Lead paints <0.1%w/w lead, compounds/alloys/products <0.1%w/w lead	0
Enclosed sprays and lagging, asbestos insulating board (with exposed face painted or encapsulated), asbestos cement sheets etc	Lead paints ≥0.1%w/w and <0.25%w/w lead	1
Unsealed asbestos insulating board, or encapsulated lagging and sprays	Lead paints ≥0.25%w/w and <1.0%w/w, Lead dusts above recommended clearance indicator based on AS/NZS4361.2	2
Unsealed laggings and sprayed asbestos	Lead dusts a multiple of at least 5 times above recommended clearance indicator based on AS/NZS4361.2, Lead paint >1.0%	3

Table 4 - Surface type or treatment

VIII. Likelihood of Disturbance

Occupant Activity

EXAMPLE OF OCCUPANT ACTIVITY	SCORE
Rare disturbance activity (eg little used store room)	0
Low disturbance activities (eg office type activity)	1
Moderate disturbance activity (eg industrial or vehicular activity which may cause contact with ACMs)	2
High levels of disturbance, (eg fire door with asbestos insulating board sheet in constant use)	3

Table 5 - Occupant Activity

Likelihood of Disturbance

FREQUENCY OF DISTURBANCE	SCORE
Usually inaccessible or unlikely to be disturbed	0
Minimal likelihood for disturbance	1

Likely disturbance	2
Frequent disturbance	3

Table 6 - Likelihood of Disturbance

Human Exposure Potential

FREQUENCY OF HUMAN EXPOSURE POTENTIAL	SCORE
Infrequent	0
Monthly	1
Weekly	2
Daily	3

Table 7 - Human Exposure Potential

Appendix A (Photographs)



External, GF, Exterior, West, Eaves, Perimeter of electrical room - Fibre Cement Sheet, Chrysotile & Amosite Asbestos detected, Previously sampled, same as B17399S01



External, GF, Exterior, Eaves, Perimeter of main amenities - Fibre Cement Sheet, Chrysotile & Amosite Asbestos detected, Previously sampled B17399S01




External, GF, Exterior, External cream paint system - Cream - Topcoat, Lead Detected (1.0%w/w), Previously sampled 17399-S05



External, GF, Exterior, External green paint system - Green - Topcoat, Lead detected, 437871-LP01



Internal, GF, Central (north) storeroom (Cricket storeroom), Ceiling -



Internal, GF, Central (south) storeroom (Dog club), Ceiling - Fibre Cement

Fibre Cement Sheet, Chrysotile & Amosite Asbestos detected, Previously sampled, similar to B17399S02



Internal, GF, Electrical board room (western side), Ceiling - Fibre Cement Sheet, Chrysotile & Amosite Asbestos detected, Previously sampled, similar to B17399S02

Sheet, Chrysotile & Amosite Asbestos detected, Previously sampled, similar to B17399S02



Internal, GF, Electrical board room (western side), West, Wall - Electrical backing board, No Asbestos Detected, Visually identified



Internal, GF, Men's toilet, Ceiling - Fibre Cement Sheet, Chrysotile & Amosite Asbestos detected, Previously sampled, similar to B17399S02



Internal, GF, Men's toilet, Mens urinal cistern - Moulded Fibre Cement, No Asbestos Detected, Previously sampled B17399S03



Internal, GF, North west corner storeroom/toilet, Ceiling - Fibre Cement Sheet, Chrysotile & Amosite Asbestos detected, Previously sampled, similar to B17399S02



Internal, GF, South West Room (kitchen), Ceiling - Fibre Cement Sheet, Chrysotile & Amosite Asbestos Detected, Previously sampled B17399S02



Internal, GF, Women's toilet, Ceiling - Fibre Cement Sheet, Chrysotile & Amosite Asbestos detected, Previously sampled, similar to B17399S02



Internal, GF, Women's toilet, Women's toilet cistern - Moulded Fibre Cement, No Asbestos Detected, Previously sampled B17399-S7

Appendix B (Site Plan - Map)



Appendix C (Analysis Report)



LABORATORY ANALYSIS REPORT Asbestos Identification Report

Report No: B17399-R1
Client: Blue Mountains City Council
Client Address: 2-6 Civic Place,
Katoomba, NSW, 2780

Report Date: Monday, 11 December 2017
Analysed Date: Monday, 11 December 2017
Laboratory Receipt Date: Monday, 11 December 2017
Sampled Date: Friday, 8 December 2017

Attention: Rick Harris
Sampled From: Lomatia Park, 32-44 Bland Road,
Springwood NSW 2777

Approved Identifier and Signatory: Jeffrey Sargent

Test Method: Polarised Light Microscopy (PLM) including Dispersion Staining (DS), Regional EnviroScience Pty Ltd in-house laboratory method, in accordance with Australian Standard AS4964-2004 'Method for the qualitative identification of asbestos in bulk samples'. Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Sample Description	Sample Size	Asbestos Detected	Fibres Detected
B17399-S1	Eaves	Fibre cement	0.7 gm	Yes	Chrysotile, Amosite
B17399-S2	Food Store	Fibre cement	0.3 gm	Yes	Chrysotile, Amosite
B17399-S3	Urinal Cistern	Moulding	0.5 gm	No	None
B17399-S4	Men's Pan Cistern	Moulding	0.2 gm	No	None
B17399-S7	Women's Cistern	Moulding	0.4 gm	No	None



REGIONAL ENVIROSCIENCE PTY LTD
 NATA Accreditation No. 19366
 ACN 157 918 262
 Ph 1300 372 436
www.enviroscience.com.au

DUBBO
 2/7 Energy Place
 Dubbo NSW 2830

SYDNEY
 2/2-4 Hale Street
 Botany NSW 2019

WAGGA WAGGA
 12 Chaston Street
 Wagga Wagga NSW 2650

TAMWORTH
 4/158 Marius Street
 Tamworth NSW 2340

MAROOCHYDORE
 1B/48 Aerodrome Road
 Maroochydore QLD 4558



LABORATORY ANALYSIS REPORT
Estimation of Airborne Asbestos Fibres

Report No: A17399-R1
Client: Blue Mountains City Council
Client Address: 2-6 Civic Place,
Katoomba, NSW, 2780

Report Date: Monday, 11 December 2017
Analysed Date: Monday, 11 December 2017
Laboratory Receival Date: Monday, 11 December 2017
Sampled Date: Friday, 8 December 2017

Attention: Rick Harris
Sampled From: Lomatia Park, 32-44 Bland Road,
Springwood NSW 2777

Test Method: In accordance with the (NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Report Date: Monday, 11 December 2017
Analysed Date: Monday, 11 December 2017
Laboratory Receival Date: Monday, 11 December 2017
Sampled Date: Friday, 8 December 2017

Sampled By: Phill Abbott
Approved Counter and Signatory: Jeffrey Sargent
Type of Monitoring: Background Monitoring

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A17399-S1	Mid Storeroom	0922	1102 100 min	4.0	0 /100	< 0.01
A17399-S2	West External	0922	1102 100 min	4.0	0 /100	< 0.01
A17399-S3	Quality Control Laboratory Blank	0922	1102 100 min	N.A.	0 /100	Acceptable limit





Envirolab Services Pty Ltd
 ABN 37 112 535 645
 12 Ashley St Chatswood NSW 2067
 ph 02 9910 6200 fax 02 9910 6201
 customerservice@envirolab.com.au
 www.envirolab.com.au

CERTIFICATE OF ANALYSIS 181885


Client Details	
Client	Regional Enviroscience
Attention	Juliet Duffy, Gemma Murphy
Address	PO Box 1645, Dubbo, NSW, 2830

Sample Details	
Your Reference	<u>17399</u>
Number of Samples	2 Paint
Date samples received	12/12/2017
Date completed instructions received	12/12/2017

Analysis Details
 Please refer to the following pages for results, methodology summary and quality control data.
 Samples were analysed as received from the client. Results relate specifically to the samples as received.
 Results are reported on a dry weight basis for solids and on an as received basis for other matrices.

Report Details	
Date results requested by	19/12/2017
Date of Issue	15/12/2017
NATA Accreditation Number 2901. This document shall not be reproduced except in full.	
Accredited for compliance with ISO/IEC 17025 - Testing. Tests not covered by NATA are denoted with *	

Results Approved By
 Long Pham, Team Leader, Metals

Authorised By

 David Springer, General Manager

Envirolab Reference: 181885
 Revision No: R00



Client Reference: 17399

Lead in Paint			
Our Reference		181885-1	181885-2
Your Reference	UNITS	S05	S06
Date Sampled		08/12/2017	08/12/2017
Type of sample		Paint	Paint
Date prepared	-	14/12/2017	14/12/2017
Date analysed	-	14/12/2017	14/12/2017
Lead in paint	%w/w	1.0	<0.05

Envirolab Reference: 181885
Revision No: R00

Page | 2 of 6

Client Reference: 17399

Method ID	Methodology Summary
Metals-004	Digestion of Paint chips/scrapings/liquids for Metals determination by ICP-AES/MS and or CV/AAS.

EnviroLab Reference: 181885
Revision No: R00

Page | 3 of 6

Client Reference: 17399

QUALITY CONTROL: Lead in Paint				Duplicate				Spike Recovery %		
Test Description	Units	PQL	Method	Blank	#	Base	Dup.	RPD	LCS-2	[NT]
Date prepared	-			14/12/2017	[NT]	[NT]	[NT]	[NT]	14/12/2017	[NT]
Date analysed	-			14/12/2017	[NT]	[NT]	[NT]	[NT]	14/12/2017	[NT]
Lead in paint	%w/w	0.05	Metals-004	<0.05	[NT]	[NT]	[NT]	[NT]	88	[NT]

Envirolab Reference: 181885
Revision No: R00

Page | 4 of 6

Client Reference: 17399

Result Definitions	
NT	Not tested
NA	Test not required
INS	Insufficient sample for this test
PQL	Practical Quantitation Limit
<	Less than
>	Greater than
RPD	Relative Percent Difference
LCS	Laboratory Control Sample
NS	Not specified
NEPM	National Environmental Protection Measure
NR	Not Reported

Quality Control Definitions	
Blank	This is the component of the analytical signal which is not derived from the sample but from reagents, glassware etc, can be determined by processing solvents and reagents in exactly the same manner as for samples.
Duplicate	This is the complete duplicate analysis of a sample from the process batch. If possible, the sample selected should be one where the analyte concentration is easily measurable.
Matrix Spike	A portion of the sample is spiked with a known concentration of target analyte. The purpose of the matrix spike is to monitor the performance of the analytical method used and to determine whether matrix interferences exist.
LCS (Laboratory Control Sample)	This comprises either a standard reference material or a control matrix (such as a blank sand or water) fortified with analytes representative of the analyte class. It is simply a check sample.
Surrogate Spike	Surrogates are known additions to each sample, blank, matrix spike and LCS in a batch, of compounds which are similar to the analyte of interest, however are not expected to be found in real samples.
Australian Drinking Water Guidelines recommend that Thermotolerant Coliform, Faecal Enterococci, & E.Coli levels are less than 1cfu/100mL. The recommended maximums are taken from "Australian Drinking Water Guidelines", published by NHMRC & ARMC 2011.	

Envirolab Reference: 181885
Revision No: R00

Page | 5 of 6

Laboratory Acceptance Criteria

Duplicate sample and matrix spike recoveries may not be reported on smaller jobs, however, were analysed at a frequency to meet or exceed NEPM requirements. All samples are tested in batches of 20. The duplicate sample RPD and matrix spike recoveries for the batch were within the laboratory acceptance criteria.

Filters, swabs, wipes, tubes and badges will not have duplicate data as the whole sample is generally extracted during sample extraction.

Spikes for Physical and Aggregate Tests are not applicable.

For VOCs in water samples, three vials are required for duplicate or spike analysis.

Duplicates: <5xPQL - any RPD is acceptable; >5xPQL - 0-50% RPD is acceptable.

Matrix Spikes, LCS and Surrogate recoveries: Generally 70-130% for inorganics/metals; 60-140% for organics (+/-50% surrogates) and 10-140% for labile SVOCs (including labile surrogates), ultra trace organics and speciated phenols is acceptable.

In circumstances where no duplicate and/or sample spike has been reported at 1 in 10 and/or 1 in 20 samples respectively, the sample volume submitted was insufficient in order to satisfy laboratory QA/QC protocols.

When samples are received where certain analytes are outside of recommended technical holding times (THTs), the analysis has proceeded. Where analytes are on the verge of breaching THTs, every effort will be made to analyse within the THT or as soon as practicable.

Where sampling dates are not provided, Envirolab are not in a position to comment on the validity of the analysis where recommended technical holding times may have been breached.

Measurement Uncertainty estimates are available for most tests upon request.



ANALYTICAL REPORT



Accreditation No. 2562

CLIENT DETAILS

Contact **Lab**
 Client **JMB ENVIRONMENTAL CONSULTING PTY LTD**
 Address **PO Box 807
 NSW 2226**

Telephone **(Not specified)**
 Facsimile **(Not specified)**
 Email **lab@jmbec.com.au**

Project **S222077-J221058**
 Order Number **S222077-J221058**
 Samples **1**

LABORATORY DETAILS

Manager **Huong Crawford**
 Laboratory **SGS Alexandria Environmental**
 Address **Unit 16, 33 Maddox St
 Alexandria NSW 2015**

Telephone **+61 2 8594 0400**
 Facsimile **+61 2 8594 0499**
 Email **au.environmental.sydney@sgs.com**

SGS Reference **SE239010 R0**
 Date Received **11/11/2022**
 Date Reported **17/11/2022**

COMMENTS

Accredited for compliance with ISO/IEC 17025 - Testing. NATA accredited laboratory 2562(4354).

SIGNATORIES

Kamrul AHSAN
 Senior Chemist

SGS Australia Pty Ltd
 ABN 44 000 964 278

Environment, Health and Safety

Unit 16 33 Maddox St
 PO Box 6432 Bourke Rd BC

Alexandria NSW 2015
 Alexandria NSW 2015

Australia t +61 2 8594 0400
 Australia f +61 2 8594 0499

www.sgs.com.au



ANALYTICAL RESULTS

SE239010 R0

Metals in Paint by ICPOES [AN065/AN320] Tested: 17/11/2022

			437871/LP01
			PAINT
			-
			1/11/2022
PARAMETER	UCM	LOR	SE239010.001
Lead, Pb	%w/w	0.001	1.6



METHOD

METHODOLOGY SUMMARY

AN065/AN320

A portion of paint chips sample is digested with nitric acid to solubilise the metals into solution. Digest then analysed by ICP OES with result calculated back to the as received paint sample basis .

FOOTNOTES

<p>* NATA accreditation does not cover the performance of this service.</p> <p>** Indicative data, theoretical holding time exceeded.</p> <p>*** Indicates that both * and ** apply.</p>	<p>- Not analysed.</p> <p>NVL Not validated.</p> <p>IS Insufficient sample for analysis.</p> <p>LNR Sample listed, but not received.</p>	<p>UOM Unit of Measure.</p> <p>LOR Limit of Reporting.</p> <p>↑↓ Raised/lowered Limit of Reporting.</p>
--	--	---

Unless it is reported that sampling has been performed by SGS, the samples have been analysed as received. Solid samples expressed on a dry weight basis.

Where "Total" analyte groups are reported (for example, Total PAHs, Total OC Pesticides) the total will be calculated as the sum of the individual analytes, with those analytes that are reported as <LOR being assumed to be zero. The summed (Total) limit of reporting is calculated by summing the individual analyte LORs and dividing by two. For example, where 16 individual analytes are being summed and each has an LOR of 0.1 mg/kg, the "Totals" LOR will be 1.6 / 2 (0.8 mg/kg). Where only 2 analytes are being summed, the "Total" LOR will be the sum of those two LORs.

Some totals may not appear to add up because the total is rounded after adding up the raw values.

If reported, measurement uncertainty follow the ± sign after the analytical result and is expressed as the expanded uncertainty calculated using a coverage factor of 2, providing a level of confidence of approximately 95%, unless stated otherwise in the comments section of this report.

Results reported for samples tested under test methods with codes starting with ARS-SOP, radionuclide or gross radioactivity concentrations are expressed in becquerel (Bq) per unit of mass or volume or per wipe as stated on the report. Becquerel is the SI unit for activity and equals one nuclear transformation per second.

- Note that in terms of units of radioactivity:
- a. 1 Bq is equivalent to 27 pCi
 - b. 37 MBq is equivalent to 1 mCi

For results reported for samples tested under test methods with codes starting with ARS-SOP, less than (<) values indicate the detection limit for each radionuclide or parameter for the measurement system used. The respective detection limits have been calculated in accordance with ISO 11929.

The QC and MU criteria are subject to internal review according to the SGS QAQC plan and may be provided on request or alternatively can be found here: www.sgs.com.au/en-gb/environment-health-and-safety.

This document is issued by the Company under its General Conditions of Service accessible at www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client only. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law .

This report must not be reproduced, except in full.

Inaccessible Areas

The areas detailed below should be assumed to have asbestos present.

Controls for contaminated dust to be managed in-situ must be applied in these areas, and any vents, cracks or holes that connect the occupied space into the ceiling cavity should be sealed upon identification.

Should hazardous/potentially hazardous materials be identified during renovation and/or demolition activities, material must be sampled for expert identification and further advice.

Standard access limitation to survey type (non-destructive).

- Behind and underneath fixed wall or floor tiles, fixed boxing, panels or concealed risers or cavities within walls.
- Underneath concrete slabs, soils or ground surface soils throughout the site.
- No destructive access was conducted as part of the inspection*, therefore only areas routinely accessed were inspected to avoid decorative or structural damage. Areas like wall voids, behind wallpaper or fixed panels, under concrete slabs and any fixed risers, fixed flooring, voids or concealed spaces which would require destructive techniques were not accessed.
- All services (gas, water and electricity etc.) were live at the time of the inspection, with general safety guidelines followed as part of the Survey.
- Within plant or fixed items that were in operation at the time of the Survey or areas only accessible by demolishing or dismantling building structure or plant.
- Buried debris and services below ground surface areas.
- Inset ceilings and wall cavities and concealed service voids such as shafts, tunnels, conduits and ducts.

All item measurements are approximations only and should not be relied upon for the purpose pricing demolition or removal costs.

7. Responsibilities

Responsibilities of parties involved in the management of ACM are detailed below. It must be noted that this is not an exhaustive list and reference must be made to pertinent legislation, Codes of Practice and standards identified in **Section 14**.

IX. Controller of Premises

Under *Work Health and Safety Regulation 2017*, management responsibilities and workplace obligations fall upon the following groups:

- Person in Control of Business or Undertaking (PCBU).
- Person with Management or Control (PWMC).
- Person Carrying out Demolition or Refurbishment Work.

Under the Work Health and Safety Regulations 2017, the above mentioned group must:

- Identify any foreseeable hazard arising from the premises that has the potential to harm the health or safety of any person accessing, using or egressing from the premises.
- Identify hazards arising from the layout and condition of the premises and the presence of materials containing asbestos.
- Ensure that hazards are identified during any design of the premises and before the premises are provided for use as a place of work.
- Assess the risk of harm to the health or safety of any person arising from a hazard.
- Eliminate or control any risk to the health or safety of any persons accessing, using or egressing the premises that arise from the premises.
- Ensure all measures adopted to eliminate or control risks are properly used and maintained.
- Review risk assessments.
- Provide other persons with the information necessary to fulfil their responsibilities in identifying hazards and assessing, eliminating and controlling the associated risks.
- Provide employers with information on foreseeable hazards, assessments of risks that have not been eliminated by the controller, risk control measures and any measures an employer may need to adopt to control risk.

X. Special Responsibilities - Asbestos

Under the Code of Practice *How to Manage and Control Asbestos in the Workplace 2019* persons with control of premises used as a workplace have a duty of care to:

- Develop, implement and maintain an Asbestos Management Plan.
- Investigate the premises for the presence/possible presence of asbestos containing materials. This responsibility may not be abdicated to the Contractor.
- Develop and maintain a register of identified asbestos containing materials, including details of the location and condition of asbestos materials, risk assessments and control measures.
- Assess the condition of any asbestos containing materials that are found and the associated asbestos risks.
- Develop measures to remove asbestos materials or minimise the risks and prevent exposure.
- Ensure control measures are implemented as soon as possible and are maintained as long as

asbestos materials remain in the workplace.

- Consult with any person who may be affected by the presence of asbestos materials (e.g. building occupants, neighbours and/or all relevant contractors).

The *Work Health and Safety Regulations 2017* and Safe Work Australia Codes of Practice require full consultation, information-sharing and involvement by everyone in the workplace (including employers, workers, contractors and others) throughout the process of identifying asbestos materials, developing an Asbestos Materials Management Plan, assessing risks and developing and implementing control measures.

Under the Code of Practice *How to Safely Remove Asbestos 2019* any person with control who commissions asbestos removal is responsible for the following:

- Ensuring only a trained asbestos removalist carries out the removal of asbestos containing materials.
- Nominating person(s) to liaise with the asbestos removalist.
- Requesting asbestos removal license details from the asbestos removalist if such a license is required for the removal being undertaken.
- Establishing an Asbestos Register before asbestos removal commences.
- Providing the asbestos removalist with a copy of the site Asbestos Register before removal commences.
- Obtain and review SWMS and ARCP if required before asbestos removal takes place.
- Monitoring asbestos controls proposed for the removal are implemented and maintained.
- Obtaining a clearance certificate from an independent competent person or LAA before the asbestos removal area is accessed.

If asbestos containing materials are to be removed, the Code of Practice *How to Safely Remove Asbestos 2019* requires consultation, including employers, workers and contractors at each step of the removal process using established consultative mechanisms. Persons in adjoining properties that might also be affected by the removal must also be consulted.

XI. Employers

Under the Work Health and Safety Regulations 2017, employers must take reasonable care to identify any foreseeable hazard that may arise from the conduct of the employer's undertaking and that has the potential to harm the health or safety of an employee, or any other person legally at the employer's place of work. In particular the employer must take reasonable care to identify hazards arising from, but not limited to, work practices and work systems, repair, maintenance, dismantling and disposal of plant, hazardous substances and the presence of hazardous materials installed in a place of work, the condition of a place of work and the physical working environment including exposure to a contaminated atmosphere.

An employer must ensure that effective procedures are in place and implemented to identify hazards including, but not limited to, those present immediately prior to using the premises for the first time as a place of work, before and during the installation, erection, commissioning or alteration of plant in a place of work and whilst work is being carried out.

An employer must assess the risk of harm to the health or safety of an employee of the employer, or any other person legally at the employer's place of work, arising from any hazard identified.

An employer must eliminate any reasonably foreseeable risk to the health or safety of an employee of the

employer, or any other person legally at the employer's place of work, that arises from the conduct of the employer's undertaking. If it is not reasonably practicable to eliminate the risk, the employer must control the risk.

An employer must ensure that all measures (including procedures and equipment) that are adopted to eliminate, or control, risks to health and safety are properly used and maintained.

An employer must ensure that each new employee receives induction training that covers, but is not limited to, workplace arrangements for management of occupational health and safety, health and safety procedures relevant to the employee including the use and maintenance of risk control measures, and accessing health and safety information required under the Work Health and Safety Regulations 2017.

Particular provisions also apply to construction processes where hazardous materials exposure may occur and lead processes (refer to the Work Health and Safety Regulations 2017).

XII. Employees & Contractors

Under the Work Health and Safety Regulations 2017, an employee must, while at work, take reasonable care for the health and safety of people who are at the employee's place of work and who may be affected by the employee's acts or omissions at work. An employee must also, while at work, cooperate with his or her employer or other person so far as is necessary to enable compliance with any requirement under the Work Health and Safety Act 2011 or Regulations imposed in the interests of health, safety and welfare on the employer or any other person.

Employees and contractors must not carry out any work that may disturb ACM without referring to the site Asbestos Register and Asbestos Management Plan

XIII. Asbestos Consultant

The Asbestos Consultant is a competent person with appropriate qualifications, training and experience in the identification, assessment and management of asbestos materials.

The Consultant is to act as an independent advisor to the Site Manager and/or Property Owner on issues relating to the identification, assessment, management and control of ACM.

This Consultant's duties may include:

- Inspection, sampling and analysis of suspected asbestos containing materials.
- Assessing the risks posed by the identified asbestos containing materials.
- Developing appropriate procedures and controls for on-site management or removal of asbestos containing materials.
- Providing staff training sessions and/or site induction manuals.
- Preparing a technical specification (i.e. Scope of Works Report or Work Plan) for asbestos containing remediation projects.
- Tendering hazardous materials remediation projects.
- Providing technical supervision and monitoring during asbestos containing remediation.
- Conducting clearance inspections after asbestos remediation.
- Issuing clearance certificates if satisfied the area is safe to reoccupy

- Updating the site's Asbestos Register and Management Plan.

The Consultant is required to hold adequate and appropriate insurances for the work undertaken.

XIV. Asbestos Removalists

The Asbestos Removalist Contractor must be a competent person with appropriate qualifications, training and experience in remediation of ACM. The Contractor must hold appropriate licenses and adequate insurances for the work undertaken.

The Contractor should complete and sign appropriate Risk Assessments and Safe Work Method Statements prior to work commencing.

All asbestos remediation conducted by the Contractor should comply with the requirements specified in the regulatory framework (refer to Section 12) and the Consultants technical specification (i.e. Scope of Works Report/ Work Plan) for hazardous materials abatement.

The Contractor must develop a site-specific Asbestos Removal Control Plan for licensed asbestos removal work in consultation with their workers and the client before commencing any asbestos removal work. The client should receive a final copy of this plan before work commences.

The asbestos removalist must hold an appropriate asbestos removal license before being permitted to remove asbestos containing material. A Class A (friable) license is required for friable asbestos removal and a Class B (non-friable) license is required for non-friable asbestos removals >10m². The removalist must provide their license details to their clients. Other requirements include:

- For friable asbestos removal, and removal of >10m² of non-friable asbestos, confirmation that notification of the removal has been made to SafeWork NSW prior to any work commencing.
- Asbestos removal operatives to complete appropriate Risk Assessments and Safe Work Method Statements prior to work commencing.
- The asbestos removalist to develop a site specific asbestos removal control plan in consultation with their client before commencing any asbestos removal work. The client should receive a final copy of this plan.
- The Asbestos Removalist to ensure the removal is adequately supervised and carried out by only trained workers in a safe manner.

XV. Lead Containing Paint

- Exposure risk remains for paint below 1% w/w lead content. Disturbing paint with lead content as low as 0.1% w/w requires control measures and personal protective equipment considerations. Further risk assessment required prior to maintenance or refurbishment works.
- If the LCP is flaking or in a poor/unstable condition, repainting is recommended as soon as practicable. The surface may be prepared by using wet sanding techniques. Take care not to generate LCD or contaminate the immediate workplace or environment with water from the wet-sanding process.
- Painting over LCP is a temporary solution limited by the life of the paint. Alternatives to painting or the removal of LCP include encapsulating the paint with other materials.
- LCP in good condition should be left in place, unless major renovation and/or comprehensive refurbishment works are planned.

- Prior to demolition works, LCPs may be disposed of attached to the substrates as long as they are in good condition. If the LCPs are chalking or delaminating, the paint residues should be removed from the substrates in accordance with AS/NZS4361.2:2017 and the waste must be disposed of as a lead containing material in accordance with the NSW Environmental Protection Authority (EPA) requirements.
- An occupational hygienist should be engaged to conduct lead dust air monitoring during major removal works to ensure airborne lead concentrations do not exceed the current occupational exposure standard of 0.15 mg/m³.
- Blue Mountains Council Hazardous Materials Team is to be engaged for all lead paint related works and if deemed necessary, a lead abatement contractor will be engaged.

8. Awareness & Training

Workers, contractors and any other persons on site who may be exposed to ACM as a result of undertaking activities on the premises must be provided with information on the health and safety consequences of exposure to fibrous materials and appropriate control measures. The provision of this information must be recorded.

Information and training must be provided to persons who may be involved in asbestos removal work or asbestos related work in the workplace including workers, contractors and others. The training may include the following:


- The purpose of the training.
- The health risks associated with the ACM.
- Types, uses and likely occurrence of ACM in workplace.
- Roles and responsibilities of the trainee under the Asbestos Management Plan.
- Location, access and use of the site Asbestos Register.
- Timetable for removal/remediation of hazardous materials.
- Process and procedures required to eliminate exposure.
- Maintenance and control measures, personal protective equipment and work methods required to minimise hazardous material risk including potential contamination of other areas.
- Control levels and exposure standards for hazardous materials.
- The purpose of any air monitoring or health surveillance undertaken.

9. Signage

NSW Work Health and Safety Regulation 2017 R422, R424, R427 and R429 requires that the person with the management control of the workplace to identify asbestos containing materials and the asbestos material that has been identified to date must be labelled and ensure that it complies with the Australian Standard 1319: Safety Signs for the Occupational Environment; signage should be similar to the label detailed below.

Signage should also be placed at the entry points to the building/plant.

Examples of asbestos signage



10. Review

This Asbestos Management Plan must be reviewed whenever the Asbestos Register is reviewed. These reviews must assess all asbestos material management processes and their effectiveness.

The site Asbestos Register, including any risk assessments, must be reviewed every 5 years from date of creation or earlier where a risk assessment indicates the need or ACM has been removed and/or disturbed. Visual inspection of asbestos materials must be included in any review of the Asbestos Register.

Risk assessments should be reviewed regularly in accordance with pertinent legislation and regulation and whenever:

- there is evidence that a risk assessment is no longer valid;
- there is evidence that control measures are not effective;
- a significant change is proposed for the workplace or work practices/procedures relevant to the risk assessment;
- there is a change in the condition of the ACM; and
- ACM has been removed, enclosed or sealed.

Only competent persons may perform and revise risk assessments. A provisional timetable for review of risk assessments, the site Asbestos Register and Management Plan is outlined within the document control section of this Asbestos Management Plan.


11. Emergency Procedures

If known or suspected ACM is damaged or otherwise disturbed, the workflow in Figure 1 Emergency Procedures Chart must be consulted

In summary, the procedure is:

- stop work immediately,
- minimise the spread of contamination to other areas,
- keep risk of exposure as low as possible, and
- immediately report incident to Council on (Insert Council Number here)

Figure 1 – Emergency Procedures Chart



12. Legislation, Codes & Standards

Workplace Health and Safety in NSW is regulated under the *Work Health and Safety Act 2011* and *Work Health and Safety Regulations 2017*. In addition, a number of related Codes of Practice, Standards and guidelines pertain to the management of asbestos materials.

XVI. Legislation

- Work Health and Safety (WHS) Act NSW (2011 [reviewed 2016]).
- WHS Regulation NSW 2017.
- Ozone Protection and Synthetic Greenhouse Gas Management Regulations NSW (1996 [amended 2016]).
- NSW Protection of the Environment Operations Act (1997).

XVII. Code of Practice

- Safework NSW (2019), How to Manage and Control Asbestos in the Workplace: Code of Practice.
- Safework NSW (2019), How to Safely Remove Asbestos: Code of Practice.

XVIII. Standards

- AS/NZS4361.2 (2017) Guide to Lead Paint Management, Part 2: Residential and Commercial Buildings.
- National Occupational Health and Safety Commission (NOHSC):1012 (1994), National Standard for the Control of Inorganic Lead at Work.
- AS 1319 (1994). Safety Signs for the Occupational Environment.
- AS/New Zealand Standard (NZS) 1716 (2003), Respiratory Protective Devices.
- AS/NZS 1715 (2009), Selection, Use and Maintenance of Respiratory Protective Devices.
- Australian Commonwealth Government. (2015). Standard for the Uniform Scheduling of Medicines and Poisons, Section Seven/Appendix I: Paints or Tinters.
- Australian Standard (AS) 4964 (2004) Method for the qualitative identification of asbestos in bulk samples.
- Guidance note on the membrane filter method for estimating airborne asbestos fibres 2nd Edition [NOHSC: 3003(2005)].

13. Terms & Definitions

Term	Definition
Airborne asbestos	Fibres of asbestos small enough to be made airborne
ALMP	Asbestos/Lead Management Plan
Asbestos	The asbestiform varieties of mineral silicates belonging to the serpentine or amphibole groups of rock-forming minerals, including actinolite asbestos, grunerite (or amosite) asbestos (brown), anthophyllite asbestos, chrysotile asbestos (white), crocidolite asbestos (blue) and tremolite asbestos
Asbestos Containing Material (ACM)	Any material or product containing asbestos
Asbestos-Contaminated Dust or Debris (ACD)	Dust or debris that has settled within a workplace and is (or assumed to be) contaminated with asbestos.
Asbestos-Related work	Any work involving the removal or other disturbance of ACM
Asbestos Removalist	A person conducting a business or undertaking who carries out asbestos removal work
Asbestos Removal Work	Work involving the removal of asbestos containing materials (ACM)
Competent Person	A person who has acquired, through training, qualification or experience, the knowledge and skills to carry out specific tasks.
Duty Holder	A person who has a duty in relation to a matter under the <i>NSW Work Health and Safety Act 2011</i>
In-Situ Asbestos	Asbestos or ACM fixed or installed in a structure, equipment or plant but does not include naturally occurring asbestos.
Friable Asbestos	ACM that may readily be crumbled, pulverised or reduced to a form where fibres may be freely released
Licensed Asbestos Removal Work	Asbestos removal work carried out by a Class A or Class B licensed asbestos removalist
Non-Friable Asbestos	Material containing asbestos that is not friable asbestos, including material containing asbestos fibres reinforced with a bonding compound
NSW WHS Regulations	<i>NSW Work Health and Safety Regulations 2011</i>
PPE	Personal Protective Equipment
RPE	Respiratory Protective Equipment
RTO	Registered Training Organisation
SOP	Safe Operating Practice
Worker	People conducting work associated with council including employees, contractors, consultants, and volunteers (as defined by clause 7 of the <i>NSW WHS Act 2011</i>)
WHS	Work Health and Safety

